

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 2 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲ

ਚੈਅਰਮੈਨ,
ਦਿ ਮਿਲੇਨੀਅਮ ਸਕੂਲ,
ਸੁਨਾਮ, ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।


ਨੰਬਰ 582

ਮਿਤੀ 20-04-2023

ਵਿਸ਼ਾ:- ਸਾਲ 2023-24 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।
ਹਵਾਲਾ:- ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: TMS/SNM/23/1137 ਮਿਤੀ 01-03-2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 10,000/- (ਪੰਦਰਾਂ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) ਜੀ.ਆਰ ਨੰ: 664911 ਮਿਤੀ:20/04/2023 ਰਾਂਹੀ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।


ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ



ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 2 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।


ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਸੰਗਰੂਰ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 109, ਮਿਤੀ:10-04-2023 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


Principal
The Millennium School
Sunam (Punjab)
Affiliation No. 1631241


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 2 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।


The Millennium School
Sunam (Sangrur)

Part-II


Building Safety Report


Name of School: The Millennium School, Sunam

I have visited the above-mentioned School Building along with **Sh. Rishav Jindal (Junior Engineer)** and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity only with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority. (The School Management /owner will be responsible for renewal of Fire Fighting Certificate before its expire Date 28/10/2023 as per Certificate attached, otherwise this Certificate will deemed to be null and void.)
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31-03-2024**


Principal
The Millennium School
Sunam (Punjab)
Affiliation No. 1631241


Sub Divisional Engineer
Const. Sub Divn.No.2 PWD, B&R
Sangrur


Chairman
The Millennium School
Sunam (Sangrur)